

#88-T-08: LOW OIL PRESSURE READING INCORRECT OIL PRESS. SENDER - (Mar 13, 1987)

MODELS: 1987 R/V, G, P AND 1988 C/K WITH LB4 (VIN CODE Z), L03 (VIN CODE H), L05 (VIN CODE K), L19 (VIN CODE N) TBI ENGINES



Some 1987 R/V, G, P and 1988 C/K models with 4.3L, 5.0L, 5.7L and 7.4L engines with throttle body injection may have a low oil pressure reading at the gage. This condition may be caused by an incorrect oil pressure sender being installed in production.

If this condition is encountered, it can be repaired by using a new oil pressure sender, P/N 10069218. The new design sender can be identified by a "60" that is stamped on the hex drive portion of the sender. For installation instructions, refer to the service procedure in Section 8C of the appropriate service manual.

This condition was corrected in production beginning with the following VIN breakpoints:

1987 R/V ----- Flint Line 1 GMC HF718914 Chevrolet HF368115 Line 2 GMC HF517180
Chevrolet HF136663 Janesville GMC HJ515257 Chevrolet HJ139069 St Louis GMC HS515905
Chevrolet HS145384

1987 G Van Lordstown GMC 513772 Chevrolet 143213 Scarborough GMC 509369 Chevrolet
119458

1987 P Chassis Detroit GMC H3503077 Chevrolet H3315178

1988 C/K Pontiac GMC JE501049 Chevrolet JE103403 Ft Wayne GMC JZ500361 Chevrolet
JZIO3371 Oshawa GMC J15W576 Chevrolet J1110750

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.